

1	3.N.9.		1/16th
SW 1966	B-510	W on N	1966 B-510
NW 1966	B-510	CW	1966 B-510
NW 1908	CT7 / 25,42	E on N	1976 A-2890
NE 1951	4 / 88		
SE 1951	4 / 90		
NE 1966	B-510		
SE 1989	B-1368		
NE 1965	7 182		
<hr/>			
N $\frac{1}{4}$ 1965	3 / 29		
S $\frac{1}{4}$ 1966	B-510	SE (cc)	1966 B-510
E $\frac{1}{4}$ 1966	B-510	SE (cc)	1963 2 / 554
N $\frac{1}{4}$ 1966	B-510	SE (wc)	1988 6 / 371
W $\frac{1}{4}$ 1966	B-510	SE (cc)	1988 6 / 371
C $\frac{1}{4}$ 1966	B-510	NE (cc)	1976 A-2890
N $\frac{1}{4}$ 1976	A-2890		

2

NW

2004

B-2730

3N 9

1/16th

N $\frac{1}{4}$

2004

B-2730

2-----

3.N.9.

		Bk.	Pg.	1/16		Bk.	Pg.
SW	1966	B-510		W on S	1966	B-510	
SE	1966	B-510		W on N	1966	B-510	
NE	1966	B-510		SW	1966	B-510	
NW	1966	B-510		CS	1966	B-510	
NE	1908	CT 7	25-42	NE	1908	CT 7	40
NW	1974	A-2659					
SW	1987	6	337				

- NW A-2663

S $\frac{1}{4}$	1966	B-510	
N $\frac{1}{4}$	1966	B-510	
W $\frac{1}{4}$	1966	B-510	
C $\frac{1}{4}$	1966	B-510	
E $\frac{1}{4}$	1966	B-510	
W $\frac{1}{4}$	1974	A-2659	
E $\frac{1}{4}$		A-2663	

~~SW 1987 6 337~~

3-----

3.N.9.

Bk. Pg.

1/16

Bk. Pg.

NE 1974

A-2663

CW 1974

A-2663

NW 1974

A-2663

CN 1974

A-2663

SW 1974

A-2663

NW 1974

A-2663

~~SW~~ NW 1964 2 578

W on S 1974

A-2663

~~SW~~ F-40-159

W on S 1999

7 302

NE 2004

B-2730

N $\frac{1}{4}$ 1974

A-2663

S $\frac{1}{4}$ 1974

A-2663

E $\frac{1}{4}$ 1974

A-2663

W $\frac{1}{4}$ 1974

A-2663

~~S $\frac{1}{4}$~~ F-40-159N $\frac{1}{4}$ 1983

7 / 225

3-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
NW	1955	2	320	W on S 1966	B-510	
SW	1966	B-510				
SE	1966	B-510				
NE	1966	B-510				
NW	1966	B-510				
NW	1964	2	578			
NW	1986	B-1212				
SE	1987	6	337			

N $\frac{1}{4}$	1965	2	595
S $\frac{1}{4}$	1965	3	31
S $\frac{1}{4}$	1966	B-510	
N $\frac{1}{4}$	1966	B-510	
W $\frac{1}{4}$	1966	B-510	
E $\frac{1}{4}$	1966	B-510	
N $\frac{1}{4}$	1983	6	249-50
N $\frac{1}{4}$	1983	B-1138	

Sec. Line N Bdry. 1955 2 320

~~See corner 1955 Bk. 2 Pg. 320~~

4

3N 9

1/16th

NW	2004	B-2730
NW	2004	B-2782

4-----

3.N.9.

		Bk.	Pg.	1/16		BK.	Pg.
NE	1964	2	578	S on W	1965	B-502	
NW	1958	A-787		W on N	1986	B-1212	
SE	1955	2	320				
NE	1955	2	320				
SW	1970	B-597					
SW	1965	B-502					
NW	1965	B-502					
NE	1974	A-2663					
SE	1974	A-2663					
NE	1986	B-1212					
NW	1986	B-1212					
<hr/>							
W $\frac{1}{4}$	1965	B-502					
E $\frac{1}{4}$	1974	A-2663					
N$\frac{1}{4}$	1965	B-502					
N $\frac{1}{4}$	1986	B-1212					
N $\frac{1}{4}$	1997	7	247				

4---

3.N.9.

	bk	pg	1/16	bk	pg
NW. 1958	1	338	S.onW.Bdry	1966	B-510
NE. 1964	2	578	W.onN.Bdry	1966	B-510
NW. 1966	B510		NW.	1966	B-510
SW. 1966	B-510		CW.	1966	B-510
SE. 1966	B-510		SW.	1966	B-510
NE. 1966	B-510		CS.	1966	B-510
SW 1965	2	591	CN.	1966	B-510
<hr/> S $\frac{1}{4}$ 1965	3	32			
W $\frac{1}{4}$ 1966	B-510		MC-N.Bdry. 1887	10	13
S $\frac{1}{4}$ 1966	B-510				
N $\frac{1}{4}$ 1966	B-510				
C $\frac{1}{4}$ 1966	B-510				
E $\frac{1}{4}$ 1966	B-510				

5---

Bk. Pg.

3.N.9.1/16

Bk. Pg.

SW	1980	A-4346			
NE	1986	B-1212		W on N	
SW	1956	A-5445		W on N	2005 A-787
NW	1979	F-40-370			B-2887
SW	2002	B-2543			
NW	2002	B-2543			
NE	2004	B-2730			
NE	2004	B-2782			
NW	2005	B-2887			

S $\frac{1}{4}$	1980	A-4346
N $\frac{1}{4}$	2002	Bk 7 Pg 353

5-----

3.N.9.

		Bk.	Pg.	1/16		Bk.	Pg.
NW	1958	1	337	W on N	1958	1	336
SW	1927	B-43		S on E	1965	B-502	
NE	1958	A-787		W on N	1965	B-502	
NW	1958	A-787		CW	1965	B-502	
NW	1965	B-502					
NE	1965	B-502					
SE	1965	B-502					
SW	1965	B-502					
NW	1972	Re/ W Bin# ⁹⁸ 99					
N$\frac{1}{4}$	1958	1	336				
S $\frac{1}{4}$	1965	2	576				
N $\frac{1}{4}$	1958	A-787					
S $\frac{1}{4}$	1965	B-502					
N $\frac{1}{4}$	1965	B-502					
E $\frac{1}{4}$	1965	B-502					
W $\frac{1}{4}$	1965	B-502					

5----

3.N.9.

	bk	pg	1/16	bk.pg.
NW. 1958	1	337	W.onN.Bdry	1958 1 336
SW. 1927	B-43		S.onE.Bdry	1966 B-510
NE. 1966	B-510			
SE. 1966	B-510			
SE 1965	2	591		
SW 1966	A-1429			
SE 1970	B-597			

N $\frac{1}{4}$ 1958	1	336	
S $\frac{1}{4}$ 1965	2	576	
E $\frac{1}{4}$ 1966	B-510		
S $\frac{1}{4}$ 1966	A-1429		
N $\frac{1}{4}$ 1929	F-20-3		

6-----

3.N.9.

NE	1979	F-40-370
NW	1979	F-40-370
NW	1957	7 180
NW	1979	7 186
SW	1994	B-1776
NW	2002	B-2543
SE	2002	B-2543
NE	2002	B-2543
NE	2005	B-2887

$N\frac{1}{4}$	1979	F-40-370
$S\frac{1}{4}$	2002	B-2543
$E\frac{1}{4}$	2002	B-2543
$N\frac{1}{4}$	2005	B-2887

		Bk.	Pg.	1/16		Bk.	Pg.
SW	1952	"OSP"	85	W on N	1958	A-787	
SW	1953	A-567		N on W	1977	B-748	
NW	1969	B-584		N on E	1977	B-748	
SW	1969	B-584					
SW	1928	4	34				
SW	1923	4	27				
SW	1951	4	90				
NE	1958	A-787					
SE	1966	A-1429					
<hr/>							
N $\frac{1}{4}$	1958	A-787					
S $\frac{1}{4}$	1965	B-502					
E $\frac{1}{4}$	1965	B-502					
N $\frac{1}{4}$	1977	B-748					

6-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
NE	1965	B-502				
SE	1965	B-502				
SW	1965	B-502				
SW	1963	B-473				
NE	1972	Re/W Bin #99				
SW	1929	F-20-3				
SW	1975	C-373				
NW	1975	C-373				

N $\frac{1}{4}$	1972	Re/W Bin #100				
N $\frac{1}{4}$	1929	F-20-3				
N $\frac{1}{4}$	1975	C-373				

 Int.Pt. Riverbend #1

C-373

6-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
SW	1979	B-868				
SW	1979	B-879				
NW	1980	Re/W Bin				
SE	1980	A-4346				
SE	1956	A-5445				
SW	1956	A-5445				
SW	1972	R/W Bin #107				
NW	1972	R/W Bin #108				
SW	1989	6	407			
SW	1989	B-1368				
SW	1992	B-1583				
NW		B-587				
<hr/>						
S $\frac{1}{4}$	1989	B-1368				

6-----

3.N.9.

		BK.	Pg.	1/16		Bk.	Pg.
NW	1951	1	95	CN	1923	4	27
SW	1952	1	97				
SW	1951	4	74-80				
NW	1951	4	88				
SW	1927	B-43					
SE	1927	B-43					
SW		A-511					
SW	1921	29	69				
SW		58	42				

N $\frac{1}{4}$	1958	A-196					
N $\frac{1}{4}$	1958	1	339				
N $\frac{1}{4}$	1920	L-29	last 10 pgs.				

3.N.9.

7-----

NW	1989	B-1368	E on S	1992	7	134
SW	1991	B-1552	MC. W.line	1992		B-1583
NW	1992	B-1583	S on W			A-5860
SW		A-5860	E on S			B-678
NW	1994	B-1776	MC W.line right bank	7		318
NE	2002	B-2543				
NW	2002	Bk 7 Pg 350				

N $\frac{1}{4}$	1989	B-1368				
S $\frac{1}{4}$	1991	P-48				
W $\frac{1}{4}$	1991	B-1552				
W $\frac{1}{4}$		A-5860				
S $\frac{1}{4}$		5 / 307				
N $\frac{1}{4}$	2002	B-2543				

7-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
NE	1980	A-4346		N on E	1980	A-4346
SE	1980	A-4346		S on E	1980	A-4346
SW	1886	Hays A	pg.7	S on E.		A-5005
SW	1956	A-5445		CS	1984	A-5181
SE	1956	A-5445		CN1/16	1956	A-5445
NE	1956	A-5445		S on E	1956	A-5445
NW	1956	A-5445				
NW	1972	R/W Bin #107				
E$\frac{1}{4}$	1980	A-4346		MC N.Bdy.R.Bank	1886	Hays A 7
C $\frac{1}{4}$	1984	A-5181		MC on 1/16 line	1886	Hays A 8
W $\frac{1}{2}$	1956	A-5445				
E $\frac{1}{2}$	1956	A-5445				
C $\frac{1}{2}$	1956	A-5445				

7-----

3.N.9.

		BK.	Pg.	1/16	Bk.	Pg.
NW	1953	A-567		N on E 1966	A-1429	
SW	1968	B-563				
NW	1969	B-584				
NW	1923	4	27			
NW	1928	4	34			
NW	1950	4	74			
SE	1965	2	590			
NW	1950	4	90			
NE	1966	A-1429				
SE	1970	B-597				
NW	1975	C-373				

E $\frac{1}{4}$	1966	A-1429				
S $\frac{1}{4}$	1923	P-9	134			
E $\frac{1}{4}$	1972	Re/W	Bin#101			

7-----

3.N.9.

		BK.	Pg.	1/16		Bk.	Pg.
SW	1953	2	271	N on W	1901	S3	344
NW	1927	B-43					
NE	1927	B-43					
NW	1901	S3	344				
NW		A-511					
NW	1921	29	69				
NW		58	42				
SW	1953	A-567					

W $\frac{1}{4}$	1901	S3	344	MC W. Bdry.	1953	A-567
W $\frac{1}{4}$	1953	2	271			

7-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
NW	1965	B-502		S on E	1965	B-502
NE	1965	B-502		S on E	1973	A-2417
SE	1965	B-502		N on E	1977	B-756
NW	1963	B-473		NE	1977	B-756
SW	1963	B-473		CN	1977	B-756
SW	1967	Bk. 5	Pg. 225			
SW	1972	RE/W Bin #	102			
NW	1989	6	407			
N $\frac{1}{4}$	1965	B-502		MC W. Bdry.	1963	B-473
E $\frac{1}{4}$	1965	B-502				
W $\frac{1}{4}$	1963	B-473				
E $\frac{1}{4}$	1973	A-2417				
E $\frac{1}{4}$	1977	B-756				
W $\frac{1}{4}$	1977	B-756				
C $\frac{1}{4}$	1978	C-388	A&B			
S $\frac{1}{4}$	1978 &9	B-851				

7-----

3.N.9.

SE	1974	B678	E on S	1974	5	307
SW	1974	B-678	CN	1977	B-742	
NW	1929	F=20-3	NE	1977	B-742	
NW		C + P	N on E	1977	B-742	
SW	1977	A-3309	CN	1977	A-3106	
SW	1 977	A-3310	SE	1979	B-868	
NW	1979	B-868	CS	1979	B-868	
NW	1979	B-879	E on S	1979	B-868	
SW	1982	A-4694				

pg85

S $\frac{1}{4}$	1974	B-678	
S $\frac{1}{4}$	1974	5	312
W $\frac{1}{4}$	1977	B-742	
C $\frac{1}{4}$	1977	B-742	
E $\frac{1}{4}$	1977	B-742	
C $\frac{1}{4}$	1977	A-3106	
E $\frac{1}{4}$	1977	A-3106	
E $\frac{1}{4}$	1977	A-3154	
C $\frac{1}{4}$	1979	B-868	
E $\frac{1}{4}$	1979	B-868	
S $\frac{1}{4}$	1979	B868	

MC on E.Bdry.S.bank Nehalem Rv.
B-879

Int.Pt. Little Rock Heap C-388

8-----

3.N.9.

		Bk.	Pg.	1/16		Bk.	Pg.
SE	1970	5	45	S on W	1965	B-502	
NE	1970	B-597		S on W	1973	A-2417	
SW	1970	B-597					
SE	1970	B-597					
NW	1965	B-502					
NE	1965	B-502					
SW	1965	B-502					
SW		B-678					
SE	1989	6	387				
NW	2002	B-2543					
<hr/>							
E $\frac{1}{4}$	1970	B-597					
S $\frac{1}{4}$	1970	B-597					
N $\frac{1}{4}$	1965	B-502					
W $\frac{1}{4}$	1965	B-502					
W $\frac{1}{4}$	1972	Re/W Bin #101					
W $\frac{1}{4}$	1973	A-2417					
W $\frac{1}{4}$	1977	A-3106					

8-----

3.N.9.

		Bk.	Pg.	1/16		Bk.	Pg.
NW	1980	A-4346		N on W	1980	A-4346	
SW	1980	A-4346		S on W	1980	A-4346	
NW	1956	A-5445		S on W		A-5005	
SW	1956	A-5445		S on W	1956	A-5445	

N $\frac{1}{4}$	1980	A-4346	CW-NW 1/64	1980	A-4346
W $\frac{1}{4}$	1980	A-4346	CW-SW 1/164	1980	A-4346
C $\frac{1}{4}$	1980	A-4346			
S $\frac{1}{4}$	1980	A-4346			
E $\frac{1}{4}$	1980	A-4346			
W $\frac{1}{2}$	1956	A-5445			

8**3.N.9.****1/16th**

SW 1965 2 / 590
NE 1965 2 / 591
NE 1965 2 / 591
NW 1927 B-43
NE 1966 B-510
NE 1965 2 / 591
NW 1966 A-1429

N on W 1966 A-1429
N on W 1977 B-742
N on W 1977 B-756

N $\frac{1}{4}$ 1965 2 / 576
W $\frac{1}{4}$ 1966 A-1429
N $\frac{1}{4}$ 1966 A-1429
W $\frac{1}{4}$ 1977 B-742
W $\frac{1}{4}$ 1977 A-3154
W $\frac{1}{4}$ 1977 B-756
W $\frac{1}{4}$ 1979 B-868

9-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
SW	1970	5	45			
NW	1970	B-597				
SW	1970	B-597				
SE	1970	B-597				
NW	1965	B-502				
NE	1974	A-2663				
SW	1989	6	387			

W $\frac{1}{4}$	1970	B-597				
S $\frac{1}{4}$	1970	B-597				
W $\frac{1}{4}$	1980	A-4346				

9=====

3.N.9.

		Bk.	Pg.	1/16		Bk.	Pg.
SE	1960	1	419	S on E	1966	B-510	
NW	1966	B-510					
NE	1966	B-510					
SE	1966	B-510					
NW	1955	2	591				
NE	1955	2	320				
SE	1960	A-873					

N $\frac{1}{4}$	1965	3	32				
N $\frac{1}{4}$	1966	B-510					
E $\frac{1}{4}$	1966	B-510					

		Bk.	Pg.	1/16	Bk.	Pg.
NW	1966	B-510		W on S 1960	1	415
SW	1966	B-510		W on S 1966	B-510	
NE	1966	B-510		W on N 1966	B-510	
SE	1960	2	<u>425</u> <i>A+B</i>	W on S 1960	A-873	
NW	1955	2	320	S on W 1966	B-510	
SE	1960	A-873		W on N 1999	7	302
NE	1987	6	337			
SW	1960	1	419			
<hr/>						
S $\frac{1}{4}$	1960	1	141	See Corner 1997 Bk. 0 Pg. 337		
N $\frac{1}{4}$	1965	3	31			
W $\frac{1}{4}$	1966	B-510				
S $\frac{1}{4}$	1966	B-510				
N $\frac{1}{4}$	1966	B-510				
S $\frac{1}{4}$	1960	A-873				

10-----

3.N.9.

		Bk.	Pg.	1/16		Bk.	Pg.
SW	1960	A-873		W on N	1974	A-2663	
SW	1970	B-597					
NW	1974	A-2663					

N $\frac{1}{2}$

1974

A-2663

11-----

3.N.9.

		bk	pg	1/16		bk	pg
NW.	1966	B-510		w.om	N,Bdry	1966	B-510
NE.	1966	B-510					
SE.	1966	B-510					
SE	1965	2	593				
SW	1960	2	425	<i>A+B</i>			
SW	1960	A-873					
n NW	1987	6	337				

N $\frac{1}{4}$	1966	B-510
E $\frac{1}{4}$	1966	B-510

~~See Survey 1967 - bk 6 pg 307~~

12-----

3.N.9.

NE

F-40-371

12-- -

3.N.9.

	bk	pg
NW. 1966	B-510	
SW. 1966	B-510	
NE (cc)	2	554
SW 1965	2	593
NE 1951	4	90
NE-CC-WC	6	371
NE 1989	B-1368	

N $\frac{1}{4}$ 1966	B-510
W $\frac{1}{4}$ 1966	B-510
E $\frac{1}{4}$ 1977	B-756

CCor.NE. 1966 B-510

13-----

3.N.9.

		BK.	Pg.	1/16	Bk.	Pg.
SE	1952	2	190			
NW	1966	B-510			S on E	A-1269
SE	1966	3	53		S on E	2001 P-644
NW	1965	2	593			
SE-CC	1957	F-15-14				
SE(cc)	1975	5	368			
SE	1989 R/W	6	396			

E $\frac{1}{4}$	2001	P-644
-----------------	------	-------

MC on E	1989	6	40 2
MC Left Bank	1957	2	356
MC Rt. Bank E.	1957	2	355
MC.E. Bdry	1957		F-15-14
WC Rt. Bank	1982	6	193
MC Lt. Bank	1982	6	192

14-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
SW	1960	1	421			
NE	1965	2	593			
NW	1960	2	425	<i>A+B</i>		
SW	2000	<u>B-2357</u>				

W $\frac{1}{4}$	1960	1	414
-----------------	------	---	-----

14-----

3.N.9.

bk pg

NE. 1966

B-510

SW 1960

A-873

NW 1960

A-873

W $\frac{1}{4}$ 1960

A-873

15-----

3.N.9.

SE	2000	B-2357
SW	2000	B-2357
SW	2000	B-2369
NW	1960	1 419

15---

3.N.9.

	bk	pg	1/16	bk	pg
SW. 1960	1	420	W.onN.Bdry	1966	B-510
NW. 1966	B-510		W on N	1960	A-873
NE 1960	2	425	<u>A+B</u>		
SE 1960	A-873				
NE 1960	A-873				
NW 1960	A-873				
SW 1960	A-873				
NW 1970	B-597				
SW 1970	B-597				

C $\frac{1}{4}$	1960	1	415
S $\frac{1}{4}$	1960	1	416
W $\frac{1}{4}$	1960	1	418
N $\frac{1}{4}$	1966	B-510	
W $\frac{1}{4}$	1960	A-873	
E $\frac{1}{4}$	1960	A-873	
C $\frac{1}{4}$	1960	A-873	
N $\frac{1}{4}$	1960	A-873	
S $\frac{1}{4}$	1960	A-873	

Line tree W/Bdy 1986	6	302
----------------------	---	-----

16-----

3.N.9.

BK. PG.

1/16

BK. PG.

SW 1986

A-5357

W on S 1986

A-5446

SW 1959

A-5446

W on S 2000

B-2369

NW 1989

6 387

SE B-597

SW 1999 7 308

SW 1999 B-2318

SE 2000 B-2357

SW 2000 B-2369

SE 2000 B-2369

NE 1960 1 419

S $\frac{1}{4}$ 1959 A-5446S $\frac{1}{4}$ 2000 B-2369

Line tree E/Bdy 1986 6 302

116---

3.N.9.

		bk	pg	1/16		Bk.	Pg.
NE.	1966	B-510		W on S	1970	B-597	
NE	1960	A-873					
SE	1960	A-873	B-597				
NW	1970	5	45				
SW	1970	5	41				
NW	1970	B-597					
NE	1970	B-597					
SW	1970	B-597					
E$\frac{1}{4}$	1960	A-873					
S $\frac{1}{4}$	1970	B-597					
N $\frac{1}{4}$	1970	B-597					
W $\frac{1}{4}$	1970	B-597					

17-----

3.N.9.

SE 2000 B-2369

17-----

3.N.9.
1/16

		Bk.	Pg.		Bk.	Pg.
NW	1980	A-4346				
SE	1986	A-5357		CS	B-678	
SW	1986	A-5357		SE	B-678	
NW	1956	A-5445		CE	B-678	
SE	1959	A-5446				
NE	1989	6	387			
SW	1957	7	180			
SE	1999	7	308			
SE	1999	B-2318				

N $\frac{1}{4}$	1980	A-4346				
S $\frac{1}{4}$	1986	A-5357				
S $\frac{1}{4}$	1999	7	310			
S $\frac{1}{4}$	1999	B-2318				

17-----

3.N.9.

		Bk.	Pg.	1/16		Bk.	Pg.
NW	1965	2	590	N on W	1974	5	307
NE	1970	5	45	S on W	1974	5	306
SE	1970	5	41	N on W	1974	B-678	
NW	1970	B-597		S on W	1974	B-678	
NE	1970	B-597					
SE	1970	B-597					
NW	1965	B-502					
SW	1974	5	305				
NW	1974	B-678					
SW	1974	B-678					
<hr/>							
N $\frac{1}{4}$	1970	B-597					
E $\frac{1}{4}$	1970	B-597					
W $\frac{1}{4}$	1974	5	306				
W $\frac{1}{4}$	1974	B-678					

18-----

SW 1992 B-1624
SW A-3258
NW A-5860
SE 1957 7 180
SW 1994 P-255

3.N.9.

1/16

S on W A-2000
S on W A-1982
S on W A-2789
S on W A-5513
S on W 2000 B-2405
S on W 2001 P-644

W $\frac{1}{4}$ A-42
W $\frac{1}{4}$ A-2000
W $\frac{1}{4}$ A-1982
W $\frac{1}{4}$ 1992 B-1624
W $\frac{1}{4}$ A-3258
N $\frac{1}{4}$ 5 / 307
W $\frac{1}{4}$ 1994 P-255
W $\frac{1}{4}$ 2000 B-2405
W $\frac{1}{4}$ 2001 P-644

18**3.N.9.****1/16th**

NW	1968	B-563			
SW	1916	4 / 26,27	S on W		A-1269
NE	1965	2 / 590	S on W	1976	A-2972
SW	1959	A-810	S on W	1977	A-3156
NW	1953	2 / 271			
NE	1970	B-597			
SW		F-40-277			

W $\frac{1}{4}$	1942	A-42			
W $\frac{1}{4}$	1916	4 / 27			
N $\frac{1}{4}$	1923	P9 / 134			
W $\frac{1}{4}$	1929	F-20-3			
W $\frac{1}{4}$	1976	A-2985			

18-----

3.N.9. 1/16

SE	1974	B-678	CN	1974	B-678
NE	1974	B-678	NE	1974	B-678
SW	1974	B-678	CE	1974	B-678
NW	1974	B-678	CS	1974	B-678
SW	1977	B-762	SE	1974	B-678
NW	1977	A-3309	E on N	1974	B-678
NW	1977	A-3310	E on S	1974	B-678
			W on S	1974	B-678
<hr/> C $\frac{1}{4}$	1974	B-678	N on E	1974	B-678
E $\frac{1}{4}$	1974	B-678	S on E	1974	B-678
W $\frac{1}{4}$	1974	B-678	CN	1976	B-728
N $\frac{1}{4}$	1974	B-678	CW	1976	B-728
S $\frac{1}{4}$	1974	B-678			
W $\frac{1}{4}$	1976	B-728			
C $\frac{1}{4}$	1976	B-728			
W $\frac{1}{4}$	1978	Re/W Bin #103			

18-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
SW	1978	B-792		CN	1978-9	B-851
NE	1980	A-4346		NCN 1/64	" "	B-851
NW	1982	A-4694		CN	1979	B-868
NW	1886	Hays A	pg 7	NCN 1/64	1979	B-868
SW	1984	B-1170		E on N	1979	B-868
SE	1986	A-5357		CN	1982	A-4644
NW	1956	A-5445		N on W	1982	A-4694
NE	1956	A-5445		E on N	1992	7 134
NW	1991	B-1552				
<hr/> W $\frac{1}{4}$	1978-9	B-851		MC W.Bdy.N.Bank	Hays A	pg.7
W $\frac{1}{4}$	1978	B-792				
W $\frac{1}{4}$	1976	A-3522				
N $\frac{1}{4}$	1978-9	B-851				
C $\frac{1}{4}$	" "	B-851				
W $\frac{1}{4}$	1979	B-868				
N $\frac{1}{4}$	1979	B-868				
C $\frac{1}{4}$	1982	A-4644				
W $\frac{1}{4}$	1982	A-4694				
N $\frac{1}{4}$	1886	Hays A	7			
N $\frac{1}{4}$	1991	P-48				

18---

3.N.9.

		bk	pg		1974	5	bk pg
NW	1953	A-567		CN			311
NE	1965	B-502		W on S	1974	5	310
NW	1963	B-473		E on S	1974	5	309
NW	1967	Bk.5	Pg. 225	SE	1974	5	309
NW	1972	RE/W Bin #102		CE	1974	5	308
SW	1974	5	314	NE	1974	5	308
SE	1974	5	305	N on E	1974	5	307
SW	1974	A-2789		E on N	1974	5	307
				S on E	1974	5	306
W $\frac{1}{4}$	1953	A-567		Initial Point 1925			B-65
W $\frac{1}{4}$		B-166		MC.W. Bdry 1953			A-567
W $\frac{1}{4}$	1974	5	313				
N $\frac{1}{4}$	1974	5	312				
E $\frac{1}{4}$	1974	5	306				
S $\frac{1}{4}$	1974	5	310				
C $\frac{1}{4}$	1974	5	311				
W $\frac{1}{4}$	1975	A-2758					
W $\frac{1}{4}$	1974	A-2790					
W $\frac{1}{4}$	1974	A-2789					

19-----

3.N.9.

NW 1994 P-255

E $\frac{1}{4}$ 1999 B-2318

19----

3.N.9.

		Bk.	Pg.	1/16		Bk.	Pg.
NW	1977	B-762			E on N	B-678	
NW	1978	B-792					
SW	1983	B-1098					
SE	1983	B-1098					
NW	1984	B-1170					
NE	1986	A-5357					
NW	1992	B-1624					
NW		A-3258					
NW		A-2789					
NE	1957	7	180				
<hr/>							
E $\frac{1}{4}$ -WC	1983	B-1098					
S $\frac{1}{4}$	1983	B-1098					
E $\frac{1}{4}$		B-678					
W $\frac{1}{4}$		B-678					
E $\frac{1}{4}$	1957	7	180				

19----

3.N.9.

		Bk.	Pg.	1/16		BK.	PG.
SW	1955	1	218	N on W	1974	5	315
NW	1916	4	26-27	W on N	1974	5	310
NW	1959	A-810		E on N	1974	5	309
SW	1974	B-675		N on E	1974	5	304
SW	1974	5	316	N on W	1974	B-678	
NW	1974	5	314	N on E	1974	B-678	
NE	1974	5	305				
NW	1974	B-678					
NE	1974	B-678					
NW		F-40-277					
SW		F-40-277					
<hr/>							
W $\frac{1}{4}$	1955	1	218				
W $\frac{1}{4}$	1974	5	315				
N $\frac{1}{4}$	1974	5	310				
E $\frac{1}{4}$	1974	5	303				
N $\frac{1}{4}$	1974	B-678					

20-----

3.N.9.

NE 2000 B-2369

SE 2000 B-2369

E $\frac{1}{4}$ 2000 B-2369

20-----

3.N.9.
PG.

1/16

		BK.	
NW	1986	A-5357	
NE	1986	A-5357	
NE	1959	A-5446	
NW	1957	7	180
NE	1999	7	308
NE	1999	B-2318	
SE	2000	7	320

N $\frac{1}{4}$	1986	A-5357	
E $\frac{1}{4}$	1959	A-5446	
W $\frac{1}{4}$	1957	7	180
N $\frac{1}{4}$	1999	7	310
E $\frac{1}{4}$	1999	7	309
E $\frac{1}{4}$	1999	B-2318	
S $\frac{1}{4}$	1999	B-2318	
C $\frac{1}{4}$	1999	B-2318	
N $\frac{1}{4}$	1999	B-2318	
W $\frac{1}{4}$	1999	B-2318	

20-----

3.N.9.

		Bk.	Pg.	1/16		Bk.	Pg.
NE	1970	5	41	N on W	1974	5	304
NE	1970	B-597		N on W	1974	B-678	
NW	1974	5	305	E on S	1983	B-1098	
NW	1974	B-678					
SE	1981	6	173				
SW	1983	B-1098					
SE	1983	B-1098					

E $\frac{1}{4}$	1970,	5	42
E $\frac{1}{4}$	1970	B-597	
W $\frac{1}{4}$	1974	5	303
W $\frac{1}{4}$	1974	B-678	
W $\frac{1}{4}$ -WC	1983	B-1098	
E $\frac{1}{4}$	1983	B-1098	
S $\frac{1}{4}$	1983	B-1098	

21-----

3.N.9.

NW	1999	7	308
NW	1999		B-2318
SW	2000	7	320
NE	2000		B-2357
NW	2000		B-2369
NE	2000		B-2369
SW	2000		B-2369
SE	2000		B-2369

W on N	2000	B-2369
NW 1/16	2000	B-2369
CN 1/16	2000	B-2369

$W\frac{1}{4}$	1999	7	309
$W\frac{1}{4}$	1999		B-2318
$N\frac{1}{4}$	2000		B-2369
$C\frac{1}{4}$	2000		B-2369
$S\frac{1}{4}$	2000		B-2369
$E\frac{1}{4}$	2000		B-2369
$W\frac{1}{4}$	2000		B-2369

21-----

3.N.9.

		Bk.	Pg.	1/16		Bk.	Pg.
NE	1960	A-873		W on N	1970	B-597	
NW	1970	5	41	W on N	1959	A-5446	
NW	1970	B-597		NW1/16	1959	A-5446	
NE	1970	B-597		CW1/16	1959	A-5446	
SW	1981	6	173	CN1/16	1959	A-5446	
SW	1983	B-1098					
NW	1986	A-5357					
NW	1959	A-5446					
W $\frac{1}{2}$	1970	5	42				
W $\frac{1}{4}$	1970	B-597					
N $\frac{1}{4}$	1970	B-597					
W $\frac{1}{4}$	1983	B-1098					
W $\frac{1}{2}$	1959	A-5446					
C $\frac{1}{4}$	1959	A-5446					
N $\frac{1}{4}$	1959	A-5446					

22-----

3.N.9.

NW	1960	A-873
NE	1960	A-873
NW	1970	B-597
NW	2000	B-2357
NE	2000	B-2357
SE	2000	B-2357
NW	2000	B-2369
SW	2000	B-2369

N $\frac{1}{4}$	1960	A-873
E $\frac{1}{4}$	2000	7 319
E $\frac{1}{4}$	2000	B-2357
W $\frac{1}{4}$	2000	B-2369

23-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
NE	1900	AMA 9	163			
NE	1977	B-762				
NW	2000	B-2357				
SW	2000	B-2357				

W$\frac{1}{4}$	1912	CT 1	50
W $\frac{1}{4}$	2000	7	319
W $\frac{1}{4}$	2000	B-2357	

MC N.BK. NEH. N.FK. AMA 9 163
East Bdry.

23-----

3.N.9.

NW

1960

Bk.
A-873

Pg.

1/16

Bk.

Pg.

24-----

3.N.9.

1/16

NE. 1952
NE 1966
NE-cc 1957
NE(cc) 1975
NE 1989

Bk.	Pg.
2	190
3	53
F-15-14	
5	368
Re/W 6	396

Bk. Pg.

26-----

3.N.9.

NW	2000	B-2357
SW	2004	B-2730

27-----

3.N.9.

NE	2000	B-2357
NW	2000	B-2369
SW	2000	B-2369
SE	2004	B-2730

28-----

3.N.9.

		Bk.	Pg.	1/16		Bk.	Pg.
NW	1981	6	173	CN 1/16	WC MC	2000	B-2369
NW	1983	B-1098					
NW	2000	7	320				
NW	2000	B-2369					
SE	2000	B-2369					
NE	2000	B-2369					

N $\frac{1}{4}$ 2000 B-2369

29---

3.N.9.

		bk	pg			
SW.	1955	1	235	E on N	1983	B-1098
NE	1981	6	173			
SW	1982	6	200			
SW	1983	B-1098				
NE	1983	B-1098				
NW	1983	B-1098				
SW	1986	B-1224				
NE	2000	7	320			
NE	2000	B-2369				
<hr/>						
N $\frac{1}{4}$	1983	B-1098				
W $\frac{1}{4}$	1983	B-1098				
N $\frac{1}{4}$	1999	B-2318				

30-----			3.N.9.	
		BK.	PG.	1/16
SE	1986	B-1224		E. on S. Bdy
SW	1986	B-1224		BK. B-1224
SW	1990	B-1438		PG.
SW		A-1071		
NW		F-40-277		
SW		F-40-277		
SW	1995	7 226		

S $\frac{1}{4}$	1986	B-1224
W $\frac{1}{4}$	1987	R/W Bin#104
S $\frac{1}{4}$	1990	B-1438

30---

3.N.9.

		bk	pg		bk	pg
SW	1974	B-675		1/16		
NW	1974	B-675		E. on S. Bdry	1902	s3 390
NW	1974	5	316	CS.	1902	s3 424
NW	1974	B-678		W. on S. Bdry	1899	s3 234
SE	1982	6	200	E. on S. Bdry	1899	s3 234
NW	1983	B-1098		E. on S. Bdy	1986	6 285
NE	1983	B-1098				
SE	1983	B-1098				

S $\frac{1}{4}$	April 1955	1	235
S $\frac{1}{4}$	1900	s3	286
S $\frac{1}{4}$	1899	s3	234
W $\frac{1}{4}$	1974	B-675	
S $\frac{1}{4}$	1900	AMA 9	36
W $\frac{1}{4}$	1981	Bk. 6	Pg. 170
N $\frac{1}{4}$	1983	B-1098	
E $\frac{1}{4}$	1983	B-1098	
S $\frac{1}{4}$	1987	B-1280	

31-----

3.N.9.

1/16th

SE	1993	B-1688	W on N	2002	B-2611
SW	1994	B-1799			
NW	1995	7 226			
SE	1995	P-313			
SE	1997	B-2138			
SE	1997	B-2139			
SW	1999	B-2281			
SE	2001	B-2513			
SE	2002	B-2543			

$W\frac{1}{4}$	1994	B-1753			
$W\frac{1}{4}$	1994	B-1799			
$S\frac{1}{4}$	1997	B-2138			
$S\frac{1}{4}$	1997	B-2139			
$S\frac{1}{4}$	1998	7 271			

31-----

3.N.9.

		Bk.	Pg.	1/16	Bk..	Pg.
SE		10	15	W on S 1969	A-1850	
SE		A-691		S on W 1938	A-164	
SW	1967	Re/ W Bin #68		E on N 1902	AMA#3	37
SW	1969	A-1850		W on S 1987	B-1283	
SE	1963	A-1103				
SW		A-1013				
SE	1970	A-2038				
SE	1967-70	Re/W Bin #66				
SW		B-260				
SW	1987	B-1283				
<hr/>						
S $\frac{1}{4}$	1958	1	316	MC S.Bdry Left Bank 10		15
S $\frac{1}{4}$		A-691		MC S.Bdry Rit. Bank 10		16
S $\frac{1}{4}$	1969	A-1850		MC S.Bdry. Left Bank Hays E		49
S $\frac{1}{4}$	1950	4	83			
S $\frac{1}{4}$	1987	B-1283				

31,-----

3.N.9.

		Bk.	Pg.	1/16		Bk.	Pg.
SW	1924	"P-9"	84	W on S	1900	AMA 9	30
SW	1972	A-2283		SW	1900	AMA 9	32
SW	1958	B-380					
SW		B-387					
SE		B-387					
NW	1974	B-675					
SE	1974	A-2733					
SW	1976	B-736					
SW	1972	R/W Bin #69					
S $\frac{1}{4}$		B-286					
S $\frac{1}{4}$		B-387					
S$\frac{1}{4}$	1975	Re/w Bin #100					
N $\frac{1}{4}$	1900	AMA 9	36				
S1/4	1975	R/W Bin #105					
S1/4	1950	1	92				
S1/4	1953	F40-159					

31-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
SW	1978	A-3550		E. on N. Bdy	1986 6	285
SW	1958	B-380		E. on N. Bdy	1986 B-1224	
NE	1982	6	200	CE 1/16	B-1224	
NE	1983	B-1098		CE 1/16	1987 B-1280	
SW		A-5034		CS 1/16	1987 B-1280	
NE	1986	B-1224		W on S	1987 B-1280	
NW	1986	B-1224				
SE	1986	B-1224				
SW	1986	B-1224				
SW	1987	B-1280				
W $\frac{1}{4}$		A-5035				
W $\frac{1}{4}$	1986	B-1224				
E $\frac{1}{4}$	1986	B-1224				
N $\frac{1}{4}$	1986	B-1224				
S $\frac{1}{4}$	1986	B-1224				
C $\frac{1}{4}$	1986	B-1224				
W $\frac{1}{4}$	1987	B-1280				
N $\frac{1}{4}$	1987	B-1280				
S $\frac{1}{4}$	1987	B-1280				

31-----

3.N.9.

NW	1990	B-1438	N on W	1990	B-1438
SW	1990	B-1439	CN 1/16	1990	B-1438
SE	1950	B-286	CE 1/16	1990	B-1438
SE		B-194	W on S	1991	7 107
SE		F-41-97			
SE	R.M. 1992	7 144			
NW		A-1071			
SW		A 1071			
SE		A-2279			
NW		F-40-277			

N $\frac{1}{4}$	1990	B-1438			
S $\frac{1}{4}$	1990	B-1438			
W $\frac{1}{4}$	1990	B-1438			
W $\frac{1}{4}$		A-1071			
W $\frac{1}{4}$		A-1303; A-1738			
W $\frac{1}{4}$		A-1254			

31-----

3.N.9.

		Bk	Pg	1/16		Bk	Pg
SE	1950	4	82	E on N	1902	s3	390
SW	A-54	4	94	NE	1902	s3	390
SE	1887	10	15	Nw	1902	s3	390
NE	1902	s3	390	SW	1899	s3	286
SE	1966	B-515		W on S	1899	s3	286
SE	1962	A-1027					

W $\frac{1}{4}$	1955	1	218
W $\frac{1}{4}$	1955	1	235
S $\frac{1}{4}$	1950	4	83
S $\frac{1}{4}$	1899	s3	286
S $\frac{1}{4}$	1898	s3	206
W $\frac{1}{4}$	1972	A-2283	

MC-S, Right Bank	1877	10	16
MC-S-Left Bank	1887	10	15
MC-W, L. Bank		10	98
MC-W-Rt. Bnk		10	98
SE Cor-Lot 4		A-164	
MC-NS \checkmark	1899	s3	286

" 1265

A-1259

32-----

3.N.9.

SW	1995	P-313
SW	1997	B-2138
SW	1997	B-2139
SW	2001	B-2513
SW	2002	B-2543
SE	2004	B-2730
SE	2004	B-2782

$S\frac{1}{4}$	1995	P-313
$S\frac{1}{4}$	1999	B-2297
$S\frac{1}{4}$	2001	B-2513

32-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
SW		A-691		E on S 1963	A-1103	
SW	1963	A-1103				
SE	1963	A-1103				
SW	1962	A-1027				
SW	1970	A-2038				
SW	1967-70	Re/W Bin #66				
SE	1951	C&P 3				
SW		B-387				
SW	1974	A-2733				
SE	1977	B-743				

S $\frac{1}{4}$	1963	A-1103		W 1/64 1900	AMA 9	34
S $\frac{1}{4}$	1962	A-1027				
S $\frac{1}{4}$	1955	A-613				
S $\frac{1}{4}$	1974	A-2733				
S $\frac{1}{4}$	1900	AMA 9	34			
S $\frac{1}{4}$	1978	A-3469				

32-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
SE	1900	AMA 9	33			
SE	1979	Re/W Bin	#67			
NW	1982	6	200			
NW	1983	B-1098				
SE	1983	B-1127				
NW	1986	B-1224				
SW	1986	B-1224				
SE	1991	B-1541				

W $\frac{1}{4}$	1986	B-1224				
S 1/4	1989	Bk. 6	Pg. 401			

32-----

3.N.9.

SW	1950	B-286
SW		B-194
SW		F-41-97
SE		B-194
SE		F-41-97
SW	RM 1992	7 144
SE	1992	B-1608
SE	1992	P-85
SW		A-2279
SW	1993	B-1688

S $\frac{1}{4}$		F-41-97
S $\frac{1}{4}$		B-194
S $\frac{1}{4}$	1992	B-1608
S $\frac{1}{4}$	1992	P-85
S $\frac{1}{4}$		A-2279
S $\frac{1}{4}$		F-40-14
S $\frac{1}{4}$		F-40-14
S $\frac{1}{4}$	1993	B-1688

		BK.	Pg.	Bk.	Pg.
SE	1951	1	96		
SE	1951	4	89		
SE	1905	4	17		
SE	1887	10	12		
SW	1887	10	15		
SW	1950	4	82		
SW	1966	B-515			
SE	1899	S3	286		
SW	1968	B-553			
<hr/>					
S $\frac{1}{4}$	1950	1	93		
E $\frac{1}{4}$		1	57		
S $\frac{1}{4}$	1950	4	84		
S $\frac{1}{4}$	1899	S3	286		
S $\frac{1}{4}$	1967	B-553			
S $\frac{1}{4}$	1967	Re/W Bin #65			
S $\frac{1}{2}$		B-260			
S $\frac{1}{4}$	1977	B-743			
S $\frac{1}{4}$	1978	A-3613			

33

3N 9

1/16th

SE 2004 B-2901

SE 2005 B-2903

33-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
SW	1983	B-1127				
SW	1910	B-1540				
SW	1991	B-1541				
SW		B-194				
SW		F-41-97				
SW	1992	B-1608				
SW	1992	P-85				
NE	2000	B-2369				
SW	2004	B-2730				
SW	2004	B-2782				
$E\frac{1}{4}$	2000	B-2369				

33-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
SW	1887	10	12			
SW	1899	S3	286			
SW	1905	4	17			
SW	1951	4	89			
SW	1963	A-1103				
SW	1951	"C&P"	3			
SW	1900	AMA 9	33			
SW	1979	Re/W bin #67				

S $\frac{1}{4}$	1887	10	13
-----------------	------	----	----

S $\frac{1}{4}$

 MC N Bank Neh. R., E Bdry 1900 AMA 9

(S) MC

 10 / 13^{pg.41}

34

3N 9

1/16th

SW	2004	B-2901
SW	2005	B-2903

$E\frac{1}{4}$	2004	B-2782
$E\frac{1}{4}$	2004	B-2901
$E\frac{1}{4}$	2005	B-2903

MC-W	Bank Nehalem	2004	B-2901
	(N ₁ Sect Line)		
MC-S	$\frac{1}{4}$	2004	B-2901

34-----

3.N.9.

		Bk.	Pg.	1/16	Bk.	Pg.
SW	1977	B-743		W on S	1991	B-1541
SE	1910	B-1540				
SE	1991	B-1541				
NW	2000	B-2369				
NE	2004	B-2730				
SE	2004	B-2730				

C $\frac{1}{4}$	1910	C-20	
E $\frac{1}{4}$	1910	C-20	
E $\frac{1}{4}$		A-718	
E $\frac{1}{4}$	1947	B-104	
E $\frac{1}{4}$	1974	Re/W Bin #106	
E $\frac{1}{4}$	1978	B-813	
E $\frac{1}{4}$	1991	B-1541	
S $\frac{1}{4}$	1991 Calc.	B-1541	
W $\frac{1}{4}$	2000	B-2369	
E $\frac{1}{4}$	2004	B-2730	

(Mc N. Bank Nh.Rv. 1900 AMA 9 41
W. Bdry.)

$W\frac{1}{4}$	2004	B-2782
$W\frac{1}{4}$	2005	B-2901
$W\frac{1}{4}$	2005	B-2903

35-----

3.N.9.

Bk. Pg.

1/16

Bk.

PG.

SW	1910	B-1540
SW	1991	B-1541
NW	2004	B-2730
SW	2004	B-2730

S $\frac{1}{4}$	1956	2	337
W $\frac{1}{4}$	1947	B-104	
W $\frac{1}{4}$	1910	C-20	
W $\frac{1}{4}$		A-718	
W $\frac{1}{4}$	1974	Re/W Bin #106	
W $\frac{1}{4}$	1978	B-813	
S $\frac{1}{4}$	1990	6	491
S $\frac{1}{4}$	1991	B-1541	
W $\frac{1}{4}$	1991	B-1541	
S $\frac{1}{4}$	2004	B-2730	
W $\frac{1}{4}$	2004	B-2730	

S $\frac{1}{4}$ 1910 B-1540