


File No. 35 (Ref. FSM 7151.4) Survey No. 170
R.D. HEBO County TILLAMOOK
Merid. WILL. N.F. SLUSLAW State ORE. **#624**

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT ~~FOUND~~

W.A. ANDERSON, TILLAMOOK COUNTY ENGINEER, 1956 SET 1 1/4" PIPE - ITS TOP 1 FT. BENEATH THE SURFACE OF THE GROUND. HE SET A 4x4 WHITE POST 6" ^{FROM} ~~OF~~ THE PIPE TO THE EAST.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND ALL THE ABOVE EVIDENCE, EXCEPT THE 4x4 POST IS BROKEN OFF FLUSH WITH THE GROUND. THE TOP IS LAYING NEARBY. SCRIBE MARKS "1/6" NE LOT 4 ARE VISIBLE.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

Leonard Whitmore, Deputy County Engineer, 12-13-76

PLANE COORDINATE POSITION

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
I SET BROKEN TOP OF POST ON SOUTH SIDE OF LOWER POST WITH A PROPERTY BOUNDARY SIGN ATTACHED. TOP OF POST IS FLUSH WITH GROUND.

FOR A REFERENCE POINT, I SET A IRON POST BENEATH THE BRANCHES OF A SMALL PINE, S. 62° W, 69 1/2 FT. FROM COR. HAYSTACK ROCK S. 12° W.

A TV TRANSLATOR S. 61° E., APPROX. 1500 FT.

Signature Leonard Whitmore Title Forestry tech Division Timber Headquarters Hebo Date 12-16-76 7100-52 (13/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

LEONARD WHITMORE '66 A DEPUTY COUNTY SURVEYOR EMPOWERED TO RE-WITNESS IDENTIFIABLE ORIGINAL MONUMENTS.

g. L. G. 12-16-76

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS